

REF	N50 19 49 W115 52 24 17 E UTC-7(6) Elev 2661' A5005 E-15 LO2 H13 CAP
OPR	Fairmont Hot Springs Resort APM 250-345-0180, 250-342-1664 250-345-6311 Reg Ldg fees
PF	B-1 C-2,5, D-3,4,6
FLT PLN	NOTAM FILE CYXC
FIC	Kamloops 866-WXBRIEF
SERVICES FUEL OIL S	100LL, JA (with FSII), SP All 4,5,6
RWY DATA	Rwy 15/33 6003x100 Asphalt
	Thid 33 displ 820' Rwy 15 up 0.4%
RCR	Opr Ltd win maint
LIGHTING	15-AS(TE LO) P2, 33-AS(TE LO) P2 PAP1 rwy 15 offset 12 rgt ARCAL-123.2 type K ARCAL opr A/D beacon
COMM	
DRCO	Pacific rdo 126.7 (FISE)
ATF	tfc 123.2 5NM 5700 ASL
NAV NDB DME	D6 261 (L) N50 19 37 W115 52 36 at A/D Pvt D6 109.6 Ch33 N50 19 37 W115 52 36 at A/D Pvt
PRO	Rgt hand circuits rwy 15 (CAR 602.96)
CAUTION	Hwy overpass & p-line approx. 40 AGL crosses apch rwy 33 aprx 1250' fr rwy thid Extensive glider activity over mtns to E of A/D. Recommend only pilots familiar with lcl area use this arpt during hrs of darkness. Ngvt ops not recommended unless all 4 hazard beacons oprg. Extv bird activity in vic of rwy.